STAR WARS

DARTH VADER

BUILD THE MODEL OF THE LEGENDARY SITH LORD

PREMIUM BASE ASSEMBLY GUIDE 07



F252INS507

FANHOME


DeAgostini COLLECTIBLES

Disney · LUCASFILM
© & ™ 2026 LUCASFILM LTD.

PREMIUM BASE

In this issue, two of the LED boards located in the center of the Premium Base are fitted and connected to the circuit board.

PIECES INCLUDED












7-1 Left front LED plate
7-2 Right front LED plate
7-3 Junction connectors × 9
7-4 Base circuit board
7-5 Charging lead
7-6 Support column base
7-7 Cover for base
7-8 Spacer
SCREWS B (36 +1 extra)
SCREWS D (1+1 extra)
SCREWS E (2+1 extra)
SCREWS F (2+1 extra)

NOTE: The appearance of the pieces shown here may differ slightly from the pieces included in this issue.


STEP 1


Take the LED plates **7-1** (long wire C) and **7-2** (short wire D) and fit them into the assembly as shown, being careful not to pinch or stretch any wires. Do not fix these plates yet.



STEP 2


Identify the four wires A, B, C, and D and plug them into the sockets on the board (the sockets have a small printed letter). The wires can only be inserted into each socket in one position, do not force or twist them. Then plug in the other wires: F (power on/off); G (USB charging socket), and H (side LED light). These are also color coded, and fit into their sockets as shown, above.






STEP 3


Once all the wires are plugged in, carefully fit the circuit board into the hole provided and secure it with two type B screws.



STEP 4


Once all wires have been checked for the correct connections, fix the LED plates **7-1** and **7-2** in place with eight type B screws in each, making 16 in all.






STEP 5


Add the nine junction connectors **7-3** in the indicated positions and fix each one with two type B screws, 18 in total.






STEP 6

Fit the type D screw inside the support column base **7-6**. Cover it with the **7-8** and then secure it with two type E screws.



STEP 7

Place the assembly from the previous step on the upper front side of the base. Then turn the whole base around and fix the support by placing the cover for the base **7-7** underneath and securing it with the two type F screws.



FINAL RESULT

USING THE CHARGING LEAD

Connect the base to a power source using the charging lead **7-5**. The charging port is located below the switch. It is advisable to check the correct illumination of the base at this stage of assembly.

